

Preliminary Information

PIC6333 Intermittent Blank or Flickering Driver Information Center (DIC)

Models

Brand:	NA.	odel:	Model Years:	VIN:		Engine:	Transmissions:
Branu.	Model.		Model reals.	from	to		
Buick	Enclave		2018 - 2019	AII	All	All	All
Buick	Envision		2017 - 2018	AII	All	All	All
Buick	Regal		2017	AII	All	All	All
Chevrolet	Colorado		2017 - 2018	AII	All	All	All
Chevrolet	Cruze		2017 - 2018	AII	All	All	All
Chevrolet	Equinox		2018	AII	All	All	All
Chevrolet	Impala		2017 - 2018	AII	All	All	All
Chevrolet	Malibu		2017 - 2018	AII	All	All	All
Chevrolet	Traverse		2018 - 2019	AII	All	All	All
GMC	Acadia		2017 - 2019	AII	All	All	All
GMC	Canyon		2017 - 2018	AII	All	All	All
Involved Region or	Country	North Ame	rica				
Condition		Some customers may complain of an intermittent blank or flickering Driver Information Center (DIC) display. They may also note that this only seems to occur when playing songs via iHeart or Pandora.					
Cause		This may be the result of an instrument panel software concern.					

Correction:

If this concern is reported, check for DTCs.

If DTCs are present, this PI does not apply and normal SI diagnosis should be followed.

If no DTCs are present, this is the only concern, and it occurs intermittently, do not replace any parts as engineering is currently evaluating the concern.

Once a solution is developed, a related bulletin will be released with repair instructions.

In the meantime, changing the station/source or waiting until the end of the song should recover the screen

Warranty Information

Labor Operation	Description	Labor Time		
3480818	Check for DTCs and Evaluate Driver Information Center Operation	.3		
*This is a unique Labor Operation for Bulletin use only.				

Version History

Version	1
Modified	Created on 5/15/2018

