

F-Pace RR Velar equipped with AJ20D Diesel Engine	"No Restarts in XXXX Miles" and DEF Dosing Malfunction message	Customer symptoms are accompanied with P203B-31 stored in the PCM. Ensure that all steps from SSM 73728 & SSM 73686 for Land Rover & Jaguar respectively, has been carried out. Check for signs for excessive crusting on the DEF Injector as well as dosing abilities. Check for signs of corrosion or leaking DEF. Follow all additional checks as outlined by TOPIx. Submit a TA if further support is required.	Under Investigation
---	--	---	------------------------