

| | | | |
|---------------------|---|--|-----------------------------|
| F-TYPE Project 7 | A Customer may report that there is visible damage to the paintwork on the upper rear quarter panel area. | This may be caused by the rear window frame seals becoming damage. Revised rear quarter window seals have been produced to address this concern. Please refer to TSB JTB00607 should a customer express a concern. | JTB00607NAS1 On Sign-off |
|---------------------|---|--|-----------------------------|