

Product Bulletin

Date: 24-May-18 **Contact Number:** 734-384-7830
Bulletin # WLK052418 **Contact Name:** Walker Technical Support

Product

Part Number(s): 55096 **Application:** 00-95 Toyota Tacoma w/3.4L Eng.

Product Name: BM Premium Pipe

Issue

The pipe at the oxygen sensor fitting location was not drilled out and will not allow the oxygen sensor to be installed. The parts affected have date code 0917335 on the label.

Corrective Action

Return parts with date code 0917335 and reorder.

Include the following for any returns that need to be made:

1. Write up part on warranty credit request, mark "other" at top of page and reference bulletin #WLK052418
2. Send a copy of the packlist to: Warranty Department, One International Dr, Monroe, MI 48161
3. Mark pipe label "Attn: Quality Control" with permanent marker.
4. All affected product must be returned to Quality Control at the following address with packlist:

Tenneco Inc.
Attn: Quality Control
3160 Abbott Lane
Harrisonburg, VA 22801

