


Inspection Procedure:

1. Open the hood and check the lot code information on the V-ribbed belt.

NOTICE

If the lot information is not visible, then quickly **START** and **STOP** the engine until the lot information portion becomes visible.



2. Compare the lot code to determine between **GOOD** and **NO GOOD**.

NOTICE

- Lot Code is 8318T9ML is **NO GOOD**.
- All other Lot Codes are **GOOD**.

NO GOOD (Lot Code "8318T9ML")



3.
 - If the lot code **is not** "8318T9ML" (GOOD), then no further work is needed.
 - If the lot code **is** "8318T9ML" (NO GOOD), then replace the V-ribbed belt following the service procedure in the Shop Manual.
 - **Refer to the Shop Manual section for Elantra (Ada) > 2018 > G 2.0 MPI > Engine Mechanical System > Drive Belt > Repair Procedures**