

July 19, 2018

Version 3

Surge, Hesitation, or Judder on Upshifts

This bulletin is replaced by 16-046, Product Update: 2011–12 Odyssey Software Update for Lock-up Clutch Function

If you did Service Bulletin 12-064 on or before July 17th, 2018, make sure to use the Warranty Claim Information provided below.

WARRANTY CLAIM INFORMATION

The normal warranty applies.

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Failed Part Number
1255C1	Update the A/T or PGM-FI software.	0.2 hr	03214	03217	37805-RV0-405
A	Replace the ATF.	0.3 hr	03214	03217	

Skill Level: Repair Technician

END

CUSTOMER INFORMATION:The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.