Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin



Campaign No. 2018040003, June 2018

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: Model 906 Model Year 2016

Replace body manufacturer information label

Daimler AG (DAG), the manufacturer of Mercedes-Benz Vans, has determined that on certain Mercedes-Benz Sprinter vehicles with folding seats and a total permissible weight of under 10,000 lbs., the information label for subsequent manufacturers / final stage manufacturers contains incorrect information regarding the unloaded vehicle weight (UVW).

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Approximately 874 vehicles are affected.

Order No. V-SC-2018040003

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Procedure

Operation No.	Operation text	Time (hrs.)	Damage Code	Code
02-2236	Operations: Replace body manufacturer	0.2	58 916 57 7	NC3KLAPPKD
	information label			




Figure 1. Information Sticker

	Check				
1	Check whether the vehicle is affected by	For authorized Mercedes-Benz service partners, only the entry in the			
	the measure	"Extended VEGA Application" (EVA) system, in the "Current" tab is			
		decisive. An additional test of the affected vehicles in the workshop			
		information system (WIS) or vehicle list is thereby not necessary.			
Replace					
2	Replace information label (Figure 1)	Bonding surface must be absolutely free of dust and grease.			
	000 588 00 84 00 Heat gun	Otherwise, a sufficient degree of adhesion cannot be assured.			
		When ordering the information label (Figure 1), quote the code for the			
		measure. To do so, enter the code in corresponding field for additional			
		entries (closing number).			
		To do so, use suitable tool (e.g. heat gun) to remove information label			
		(Figure 1) and remove any adhesive residue using suitable cleaning			
		agent.			

Parts ordering note

Part no.	Designation	Quantity
A 906 584 74 06 26	Information sticker	1