

## SERVICE CAMPAIGN BULLETIN

Classification: EL10-033b Reference: ITB10-065b COPYRIGHT© NISSAN NORTH AMERICA, INC. Date:

July 17, 2018

## VOLUNTARY SERVICE CAMPAIGN 2007 – 2008 FX WITH ICC SPEEDOMETER AND ODOMETER PROGRAMMING ERROR

CAMPAIGN ID #:P0332 (Inactive)APPLIED VEHICLES:2007 – 2008 FX (S50) with Intelligent Cruise Control (ICC)

## Service Campaign ID # P0332 is No Longer Active

- Infiniti Service Campaign Bulletin ITB10-065 for Service Campaign P0332 was originally issued on October 21, 2010.
- Service Campaign ID # P0332 is no longer active.
- Repair orders opened after July 17, 2018 are no longer eligible for reimbursement under Campaign ID # P0332.
- Please discard previous versions of ITB10-065.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.