

Complaint "Seat Cover Wrinkled" (22/13)

Revisions: Revision 1 — This bulletin replaces bulletin dated April 13, 2013.

This information is now applicable for all model lines.

Model Year: As of 2012

Model Line: All model lines

Concerns: Look of the seat cover

Information: Work procedure in the event of complaint "Seat cover wrinkled".

If wrinkles or bulges are visible on a seat cover (e.g. \Rightarrow Figure 1), these do not constitute a defect.



Figure 1

7

Service

7413 ENU 22/13

Technical Information



Information

Leather is a natural product and has so-called "natural characteristics". These characteristics are:

- The larger the upholstered surface, the greater the tendency to crease and bulge.
- Body heat, perspiration and body weight cause fabric and leather to stretch, resulting in "wrinkles".

This visual change is perfectly normal and does

- not affect its use, function or service life
- and is not a defect.

 \Rightarrow If a visual flaw that is **clearly different** from the "natural characteristics" described here is found, the seat cover must be replaced:

- Sufficient documentation with corresponding pictures (clear overview and detailed photos) must be provided.
- The seat cushion is not the cause of these wrinkles and must not therefore be replaced.

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.