

August 6, 2018

Version 3

Wind Noise from the Driver's or Front Passengers Side Window

This bulletin is replaced by 18-045, *Wind Noise from the Driver's or Front Passenger's Window*

If you did service bulletin 15-011 on or before August 6, 2018, make sure to use the WARRANTY CLAIM INFORMATION provided below to file a claim.

WARRANTY CLAIM INFORMATION

The normal warranty applies.

NOTE

There is a Repair Procedure A and B for both L4 and V6 models. Make sure you are doing the correct repair procedure for the correct vehicle.

Repair Procedure A (L4)

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
8271B5	Replace right front run channel and right front trim (L4). Includes test drive	1.9 hrs	06201	07302	15-011A	72235-T2F-A02
8261C0	Replace left front run channel and left front trim (L4). Includes test drive	1.9 hrs			15-011B	72275-T2F-A02
8271B6	Replace Both right and left side run channels and front trims (L4). Includes test drive	3.8 hrs			15-011C	72235-T2F-A02

Repair Procedure B (L4)

8271B7	Replace right front trim (L4). Clean and apply EPT Sealer. Includes test drive.	0.9 hr	06201	07302	15-011G	72430-T2F-A01
8261C1	Replace left front trim (L4). Clean and apply EPT Sealer. Includes test drive.	0.9 hr			15-011H	

CUSTOMER INFORMATION:The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.

Repair Procedure A (V6)

8271B8	Replace right front run channel and right front trim (V6). Includes test drive	1.9 hrs	06201	07302	15-011D	72235-T2F-A02
8261C2	Replace left front run channel and left front trim (V6). Includes test drive	1.9 hrs			15-011E	72275-T2F-A02
8271B9	Replace Both right and left side run channels and front trims (V6). Includes test drive	3.8 hrs			15-011F	72235-T2F-A02

Repair Procedure B (V6)

8271C0	Replace right front trim (V6). Clean and apply EPT Sealer. Includes test drive.	0.9 hr	06201	07302	15-011J	72430-T2G-A01
8261C3	Replace left front trim (V6). Clean and apply EPT Sealer. Includes test drive.				15-011K	

Skill Level: Repair Technician

END