

August 6, 2018

Version 5

## Wind Noise from the Driver's or Front Passenger's Window

This bulletin is replaced by 18-045, *Wind Noise from the Driver's or Front Passenger's Window*

If you did service bulletin 15-087 on or before August 6, 2018, make sure to use the WARRANTY CLAIM INFORMATION provided below to file a claim.

### WARRANTY CLAIM INFORMATION

The normal warranty applies.

**For one side – use the following warranty information.**

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
8150B3	Clean and apply EPT sealer on the left or right side window. (Includes test drive.)	0.4 hr	07408	05604	15-087A	72235-T2F-A02

**For both sides – use the following warranty information.**

8150B3	Clean and apply EPT sealer on the left or right side window. (Includes test drive.)	0.4 hr	07408	05604	15-087B	72235-T2F-A02
A	For the opposite side - add	0.4 hr				

Skill Level: Repair Technician

END

**CUSTOMER INFORMATION:** The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.