

NEWMAR CORPORATION

WARRANTY

DEPARTMENT

RECALL SERVICE BULLETIN

DATE ISSUED	MODEL YEAR(S) AFFECTED	RSB #
8/24/2018	2018	526

MODEL

Bay Star Sport	<input checked="" type="checkbox"/>	Ventana	<input checked="" type="checkbox"/>	Essex	<input checked="" type="checkbox"/>
Bay Star	<input checked="" type="checkbox"/>	Dutch Star	<input checked="" type="checkbox"/>	King Aire	<input checked="" type="checkbox"/>
Canyon Star	<input checked="" type="checkbox"/>	Mountain Aire	<input checked="" type="checkbox"/>	New Aire	<input checked="" type="checkbox"/>
Ventana LE	<input checked="" type="checkbox"/>	London Aire	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>

DESCRIPTION

Newmar Corporation has decided that a defect relating to motor vehicle safety exists in specific motorhomes.

NHTSA # 18V 438, TC# 2018-349

Issue: After the battery disconnect is turned on, the slideout controller may cause the slideouts to extend or retract without warning. This could increase the risk of injury and/or damage to property. This condition can only occur with the battery disconnect on and the ignition key in the off/accessory position.

Correction: Dealers will replace the slideout controller.

This recall applies only to specific 2018 coaches. Please refer to the attached population list for specific production numbers and VINs of affected coaches.

RECOMMENDED ACTION

Contact your Newmar Service Account Manager to obtain authorization. Know which slideout(s) the controller(s) operates so the correct controller(s) can be shipped. The parts department will ship the parts once they are available for this repair after September 10, 2018.

Follow the attached instructions to complete the recall.

Flat rate code: 18V 438

Labor time: .5 hr.

Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.