



Technical Service Bulletin

34 Squeaking noises from MTF pump

34 18 34 2051575/1 June 27, 2018.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6	2016-2018	All	0CK transmission
A4, A4 allroad	2017-2018	All	0CK, 0CL or 0CJ Transmission
A5	2018	All	0CL or 0CJ Transmission
Q5	2018	All	0CJ Transmission

Condition

Customer states:

- Squeaking noises from under the vehicle.

Workshop findings:

- The noise can be traced to the MTF pump V553. When removing the connector of the pump the noise is gone.

For an example of the sound, see the video located at:
<https://audi-external.kzoplatform.com:443/swf/player/361> (Figure 1).



Figure 1. QR code for squeaking noise.

Technical Background

Not applicable.



Technical Service Bulletin

Production Solution

Not applicable.

Service

If the noise can be duplicated from the MTF pump V553, then replace the MTF pump V553.

Warranty

Claim Type:	<ul style="list-style-type: none">• 110 up to 48 Months/50,000 Miles.• G10 for CPO Covered Vehicles – Verify Owner.• If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	3472		
Damage Code:	0020		
Labor Operations:	Oil pump remove + reinstall	3472 1900	70 TU
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to service procedure	0121 0002	10 TU
	Road test after service procedure	0121 0004	10 TU
Claim Comment:	As per TSB #2051575/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
N 91173601	Flange Screw	04
0CK321281K	Oil Pump	01



Technical Service Bulletin

Additional Information

All parts and service references provided in this TSB (2051575) are subject to change and/or removal. . Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2018 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.