On-car analysis list from September 10th, 2015 please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Jetta, Golf, Passat	15	2.0TDI CVCA/CRUA	All	Oil Light	Customer states the oil light is on
	Jetta Hybrid	13 - 15	All	All	P309F and P309D Fault Code	Mil-on no electric drive mode, untouched vehicles
	Jetta, Passat, Beetle, Beetle Conv	14-15	1.8T (CPRA, CPKA) 2.0T (CPPA, CPLA)	All	Map Sensor	Mil-on with fault code P0068 and/or P1158, untouched vehicles
	Passat	12-13	3.6L (CDVB)	All	Cat Converter	Mil-on with fault code P0420 and P0430, untouched vehicles (Must contain both faults)
	Golf, Jetta, Passat, Golf Sportwagen, Beetle, Beetle Conv	15	2.0TDI (CVCA, CRUA)	All	Glow Plug	MIL-on with glow plug pressure sensor faults and a confirmed loose glow plug connector with no previous repairs
	Tiguan, EOS, CC	12-15	All	All	P2015 in ECM	Mil-on with fault code P2015
	Tiguan	15	All	All	P0455 in ECM	MIL-on with P0455 (untouched vehicle with no previous EVAP related repairs)
	Touareg	11-15	3.0L (CATA/CNRB)	All	P0087/Fuel Pump Noise/Crank-No-Start	Customer states crank no start, in-tank fuel pump making noise, possibly with P0087 (No previous repairs for High Pressure Pump concerns)
	Jetta, Passat, Beetle, Beetle Conv	15	1.8T (CPRA, CPKA) 2.0T (CPPA, CPLA)	All	Injector	MIL-on misfire faults (injector must be confirmed to be the cause of misfire)
Electrical	Passat	14-15	All	All	Backup Camera Inoperative	Backup camera is completely inoperative (static)
Chassis	Passat	14	All	All	Front brake caliper	Excess front brake dust or uneven brake pad wear (VINS EC050000 – EC065000 only) (untouched vehicles only)
Body	Passat	15	All	All	Dashboard Noise	Customer states there is a squeak or rattle from the left or right side of the dashboard (only vehicles after VIN FC054650)