



## **SERVICE BULLETIN**

**SB-18-026 P0300-SERIES DIAGNOSTIC  
TROUBLE CODE(S)**

**GROUP: 0-GENERAL  
BULLETIN NO: SB-18-026  
DATE: 9-12-2018**

**SUBJECT VEHICLES:** 16MY-19MY Conventional Trucks equipped with a J08 engine

**Note:** *Refer to the appropriate Vehicle Identification Number in the warranty system to determine any vehicle recalls or campaigns prior to performing this service bulletin.*

## **OVERVIEW:**

If a truck comes to the dealer for the MIL On (or was recently On) and the Engine Control Unit (ECU) recorded one or more of the P0300-series DTC's (P0300, P0301, P0302, P0303, P0304, P0305 and P0306), refer to the following steps:

**1.** Check for any vehicle campaigns/recalls. Are there any ECU reprogramming campaigns/recalls in the warranty system related to the truck?

- Yes – Complete the recall.
- No – Continue to Step 2.



2. Does this truck exhibit any performance concerns such as a misfire, low power or engine noise symptoms?
  - Yes – Open a TechAssist Case and attach the DX report to the case. Provide details of the concerns.
  - No – Erase all DTC's and release the truck.

**Note:** This technical service bulletin is provided as technical information and is not authorization for a warrantable repair.

## ***CLAIM APPLICATION***

*Reimbursable in accordance within the terms and policies of the Hino limited warranties.*

### **Engine ECU Reprogramming:**

Labor charge: 0.5 hour

Warranty code: 86311

Trouble code: 98

Operation code: 86530AOT

Original failed part: 9999999999

