

**** TECHNICAL INFORMATION NOTICE ****

DATE: September 24, 2018
TO: Mitsubishi Motors US & Puerto Rico Dealer Service and Parts Managers
RE: Coolant Leaking from Water Hoses at CVT8 Fluid Cooler
TIN NO. TIN-18-23-004

AFFECTED VEHICLES: 2016 - 2018 Outlander Sport equipped with CVT8 transmission (F1CJC/W1CJC)


PURPOSE

Dealers have reported coolant leaking from the water hoses at the CVT8 fluid cooler (see photo below). Normal dealer repairs have been to replace the water hose and/or clamps on the affected area.



(View looking up from the bottom of the vehicle)

In order to investigate this condition further, MMNA is looking to collect 3 complete sets of CVT8 fluid coolers with the water hoses and clamps **undisturbed**. Please **do not remove** the water hose clamps and hoses indicated by the circled areas in the photo below (the other hoses are for the CVT8 oil, not coolant). This is important since MMC needs to perform a duplication test to confirm the area of leakage.



Please open a Techline case, attach photos of the condition, and contact Techline (800-446-6064) to review the findings. Product Support will then contact the dealership to arrange return of the original parts to MMNA.

Part Description	Part Number	Quantity
A/T Oil Cooler Assembly	2920A400	1
T/M Oil Cooler Line Hose	2922B017	1
T/M Oil Cooler Line Hose	2922B019	1
T/M Oil Cooler Line Clip (17.8)	MU660005	2