



Technical Service Bulletin

40 Noises when steering

40 18 82 2051792/1 July 13, 2018.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q3	2015 - 2019	All	Not Applicable

Condition

Customer states:

- Noises when turning the steering wheel over the full range in stationary. The concern is related to the strut mounting/bearing.

Technical Background

Not applicable.

Production Solution

Not applicable.

Service

Replace the strut ball bearing according to the instruction in Elsa at Repair Manual, *Chassis >> Suspension Strut and Upper Control Arm >> Suspension Strut, Removing and Installing.*

Warranty

Claim Type:	<ul style="list-style-type: none">110 up to 48 Months/50,000 Miles.If vehicle is outside any warranty, this Technical Service Bulletin is informational only.
Service Number:	4093
Damage Code:	0010



Technical Service Bulletin

Labor Operations:	Axial ball bearing remove + reinstall (One side)	4093 1950	20 TU
	Suspension strut remove + reinstall (One side)	4085 1900	130 TU
	Axial ball bearing remove + reinstall (Both sides)	4093 2050	40 TU
	Suspension strut remove + reinstall (Both sides)	4085 2000	220 TU
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to service procedure	0121 0002	10 TU
	Road test after service procedure	0121 0004	10 TU
Claim Comment:	As per TSB #2051792/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

The part numbers mentioned in this TSB are different than the ones listed in ETKA. Only use parts listed in this TSB, this includes superseding part numbers!		
Part Number	Part Description	Quantity
See ETKA	Fasteners, Bolts, Nuts and Screws as needed per the Repair Manual	See ETKA/ELSA
1K0412249A	Ball Bearing	01 - 02

Additional Information

All parts and service references provided in this TSB (2051792) are subject to change and/or removal.

©2018 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.