Range Rover RR Sport Discovery equipped with AJ126 Engines	A Customer may complain of a hesitation while accelerating from a 'rolling stop'.	We are investigating complaints on MY18 vehicles which had complaints from new as well as 14-17 MY vehicles where this complaint surfaced following a software update. Perform diagnosis and repair of any DTCs stored. If a repair is made and validated based on DTCs, raise an EPQR and hold any parts replaced for analysis. If the complaint is deemed to be normal as compared to another like vehicle, raise an EPQR with a video of the live data signals below, taken when the complaint occurred attached to the report. Also describe in detail what conditions cause the complaint to occur.			Under Investigatio n
		PCM:	TCM:		
		Accelerator Pedal Position	1.	Throttle Position	
		 Vehicle Speed 	2.	Engine Torque	
		 Throttle Position 	3.	Gear Position	
		 Engine RPM 	4.	Output Shaft Speed	