Range Rover
Discovery
17-18MÝ

A Customer may complaint of a no start condition.

Diagnosis leads to the starter being inoperative. Electrical testing of the circuit shows no issues. Inspect the vent tube fitting on the starter for evidence of water intrusion. If water intrusion is noted, raise an EPQR with pictures.





Under Investigation