

Reference	SSM74043
Models	Discovery / L462 Discovery Sport / L550 LR3 / L319 Range Rover / L405 Range Rover Evoque / L538 Range Rover Sport / L494 Range Rover Velar / L560
Title	InControl Touch Pro - Wireless Head Phones Inoperative
Category	Electrical
Last modified	24-Aug-2018 00:00:00
Symptom	207000 Entertainment Systems
Content	<p><u>Issue:</u> Customers may complain that the Wireless Head Phones for Dual Screen View or Rear Seat Entertainment are inoperative.</p> <p><u>Cause:</u> A number of Wireless Headphones have been returned to the supplier under warranty with the only defect found to be depleted batteries.</p> <p><u>Action:</u></p> <ul style="list-style-type: none"> • Please carefully follow the diagnosis advice in TOPIx section 415-01: Information and Entertainment System - Vehicles With: InControl Touch Pro > Diagnosis and Testing > Information and Entertainment system, section heading "WIRELESS HEADPHONES" • The headphones are sensitive to battery voltage, it is essential that only brand new batteries are used for diagnosis. <p>Technicians - Please rate this SSM and provide comments so that future communications can be improved.</p> <p>1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.</p> <p>3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.</p>

5 = Excellent – All required information provided to resolve the customer concern.