

Subject

**Squeak Noise from Front of Vehicle On Uneven Surfaces - FR RH (No.1) Body Mount Bushing
Squeak Noise from Front of Vehicle On Uneven Surfaces - FR RH (No.1) Body Mount Bushing**

Market

USA

Service Category

Suspension

Applicability

2016-2018 MY Tacoma

Section

Front Suspension

APPLICABLE VEHICLES

2016-2018

Tacoma

CONDITION

Some 2016-2018 model year Tacoma vehicles may exhibit a squeak or rattle noise from the FR RH (No.1) Body Mount Bushing when driving over uneven roads or bumps. Make sure to confirm that the noise is coming from the FR RH (No.1) Body Mount Bushing before proceeding.



Location of FR RH (No.1) Body Mount

RECOMMENDATIONS

After confirming the noise from the FR RH (No.1) Body Mount, submit the following information in a DPR:

1. BEFORE uninstalling the bolt from the FR RH (No.1) Body Mount, take a photo of the bushing condition and position in relation to the frame.



Example of bushing condition photo

Subject

**Squeak Noise from Front of Vehicle On Uneven Surfaces - FR RH (No.1) Body Mount Bushing
On Uneven Surfaces - FR RH (No.1) Body Mount Bushing**

Market

USA

Applicability

RECOMMENDATIONS

- After the bolt is removed, take a photo of the bolt witness mark on the body and note the direction of the offset. (see below for detail)



Location of Bolt top mounting surface and witness mark example

LINK REFERENCES

This Tech Tip does not contain any link references