XCL	A Customer may report "Hood Open" message displays on IP with hood closed.	A customer may report the "Hood Open" message displays on the Instrument cluster when the hood is latched closed. This may be caused by a hood latch switch that is away from specification. TSB JTB00619 & LTB01149 has been reissued to change the assured build date on the hood latch to 27/04/18. Please ensure the latest version of the bulletin is referenced when checking the latch.	JTB00619NAS2 LTB01149NAS2
-----	--	--	------------------------------