

Discovery Sport 16MY-Onward	A Customer may report that the gesture tailgate unintentionally opens when the vehicle is stationary and smart key is within range.	This may be caused by the gesture tailgate module wiring harness that was not routed correctly. Should a customer express a concern, please refer to TSB LTB01198 to check the gesture tailgate wiring harness routing to ensure is it correct.	LTB01198NAS1
--------------------------------	---	---	--------------