



Technical Journal

TITLE:

Outer rear view mirror folding issue

REF NO: TJ 33186.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2017-11-14	STATUS DATE: 2017-11-20
FUNC GROUP: 8460	FUNC DESC: Outside mirrors	Page 1 of 2	

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
246							2018-2018		0000390-0007839	201717-201728

CSC Customer Symptom Codes

Code	Description
3I	Door mirrors/Folding does not work
XP	Door mirrors/Folding does not work

VST Operation Number

VST Operation Number	Description
36004-2	Software control module downloading

DTC Diagnostic Trouble Codes

Text

**DESCRIPTION:**

If the vehicle shows the symptom of the outer rear view mirror not folding correctly, Follow advise under service.

SERVICE:

Perform a total software upgrade according to TJ 31543.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8460.