



Technical Journal

TITLE:

Remote control key disturbances

REF NO: TJ 30499.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2017-10-17	STATUS DATE: 2017-11-07
FUNC GROUP: 3669	FUNC DESC: Miscellaneous	Page 1 of 2	

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
234							2017-9999		-	201617-999952
235							2017-9999		-	201617-999952
236							2017-9999		-	201617-999952
246							2018-9999		-	201717-999952
256							2016-9999		-	201505-999952

CSC Customer Symptom Codes

Code	Description
XM	Alarm/Other alarm problems
VZ	Locking/unlocking/Other central locking problems
1J	Remote control/Mechanical problem/Key unit only
7G	Text window and warning symbol/Yellow symbol and text message
FB	Text window and warning symbol/Other problems
IV	Text window and warning symbol/Text message

VST Operation Number



DTC Diagnostic Trouble Codes

Text

DESCRIPTION:

This TJ is released to highlight the importance of not storing the remote control key close to objects that may shield radio communication between the remote control key and the car or could cause interference with they key signals.

Avoid storing the remote control key near metallic objects or electronic devices, e.g. laptops, tablets, mobile phones or chargers. In select cases, these may prevent key communication with the vehicle.