

**Measure no.**

US 62067656-01

**Subject**

Navigator V (5) does not link up via the cradle

**Status date (mm/dd/yy)**

8/20/15

**Status**

Accepted

**Organization**

US, MOT

**Date created (mm/dd/yy)**

8/20/15

**Created by**

Martin Bumba

**PQM Problem reference****Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

**Vehicles affected****E series**

K49

**Engine****Body****Production period (from/to)**

(mm/dd/yy)

**Comment on production period**

/

**Feedback (all cases relating to**

measure up to) (mm/dd/yy)

**Complaint**

The Navigator V (5) does not link with the motorcycle when mounted in the cradle.

**Cause**

Cradle harness is plugged into the wrong connector.

**Measure**

The OA connector for the cradle is located on the left side of the vehicle.

See Workshop installation instructions 77 52 008 in the latest RSD.

**Complaint**

	<b>Fault location</b>	<b>Fault type</b>	<b>Fault place</b>
▶	65/90 Mount cradle	Incorrectly connected	

**Cause**

	<b>#</b>	<b>Fault location</b>	<b>Fault type</b>	<b>Fault place</b>
▶	1	65/90 Mount cradle	Electrical system: Not connected	

**Repair Task**

**Special Clearance**

**Area**

No

Electrics/Electronics

---

**Fault code**

---

**Progman / DIS / ISTA / ISTA/P**

**System**

**State**

**Version**

---

© 2002-2015 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.

