

**Volvo Models****Volvo Model** VNL , VNM , VHD , VAH**Engine family**

Engine family 11L Engine , 13L Engine

**Emission Standard**

Emission Standard US16 , US14 , US14+OBD13 , US14+OBD15 , US14+OBD16

**\*\* SOLUTION \*\*****Title** Volvo Chassis - Vehicles Equipped With Two-Piece Valve Cover - [FSB 211-002 Two Piece Valve Cover Name Plate, Replacement](#); Name Plate Loose Or Missing - Model Year 2015 To 2018**Cause**

The name plate on a two piece valve cover, the name plate may come loose. Over time, weak clips in combination with water absorption in the plastic may lead to the deformation of the name plate.

**Solution**

On some VOLVO VN, VHD, and VAH trucks built from January 2014 to July 2017 and equipped with the name plate on a two piece valve cover, the name plate may need to be reattached. Refer to [FSB 211 - 002](#), Two Piece Valve Cover Name Plate, Replacement - for more information ref to [FSB 211 - 022](#) in the [eMEDIA](#) CENTER.

**Function(s)/component(s) affected**

Function affected FSB

**Function Group**

Function Group 211 cylinder head

**Customer effect**

Main customer effect visual appearance

Visual appearance loose , distortion , part lost/missing function

**Administration**

Author RU4469V

Dealer ID RU4469V

Last modified by A241298

Creation date 01-10-2018 22:10

Date of last update 03-10-2018 20:10

Status Published