



KLE CHARGING FAULT 21E6E9

MODEL

F30 PHEV

SITUATION

During the ISTA short test diagnosis, fault code 21E6E9 – “Charging interruption” is found stored in the KLE (Convenience Charging Electronics) module. There is no customer complaint related to charging system, or a warning check control message display.

CAUSE

An Erroneous fault 21E6E9 stored in the KLE after completion of AC charging session.

PROCEDURE

Evaluate the EME (Electrical Machine Electronics) and KLE fault memories.

Are there any other fault codes stored related to the charging system?

NO - ignore KLE FC 21E6E9 and delete it

YES - continue diagnosis with the appropriate ISTA test plan

WARRANTY INFORMATION

Not applicable.

[Copyright ©2016 BMW of North America, Inc.]