



SUBJECT

Headunit-High: INITIAL Enabling Code Is Not Accepted Via I-Drive

MODEL

F01

F02

F02H

F06

F07

F10

F10H

F12

F13

F15

F22

F25

F30

F30H

F31

F32

F33

F34

Produced from July 2013 (MY14 vehicles)

With option 609 (Navigation System Professional, HU-H)

and

Without option 6VA (CIC contribution)

SITUATION

The navigation system part of the Headunit-High (HU-H) cannot be activated when entering the 20-digit INITIAL enabling code manually via the iDrive controller.

CAUSE

Application error in the Headunit-High (HU-H).

INFORMATION

Do not replace any parts.

NOTE: First time activation of the navigation system should always be performed during the Quality Certification 1 (QC1) Pre-Delivery Check, with the vehicle connected to the diagnosis system ISTA. Refer to [SI B65 30 09](#).

Connect the vehicle to the diagnosis system ISTA and activate the navigation system. The code is entered when running the QC1 Pre-Delivery Check test module. Refer to [SI B09 04 09](#).

IMPORTANT: No programming is required.

WARRANTY INFORMATION

Not applicable since the first time activation of the navigation system is part of the QC1 process and cannot be claimed separately.

[Copyright ©2014 BMW of North America, Inc.]