

## GPOP - Issue Review System

**Part Number:** 68090604A\$, 68090602A\$

**Part Description:** Power Transfer Unit

**Issue** Prior to replacing the PTU, please review the following .~

**Description:** Check if the service 4WD light is intermittent by driving under heavy throttle will produce a C1494-92 DTC, if yes, please call FCA axle engineering and do not replace the PTU. Bruce Michel at cell (248) 260-8641, or Jian Zhu at cell (248) 379-1132. If neither answers with 15 minutes then proceed with the repair. ~  
If the service 4WD light lamp is on steady then replace the Power Transfer Unit. ~

~\_\_\_\_\_~  
Contact Us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.