

GPOP - Issue Review System

Part Number: 68249197A\$, 68249200A\$, 68249201A\$, 68249202A\$

Part Description: Tire pressure sensor

Issue Description: Ram trucks Built after November 2014, with a TPM lamp on and Active trouble codes: C1501-31, C1502-31, C1503-31, C1504-31, C1505-31, or C1506-31 No sensor signal.~

Prior to replacing any components please contact Raja Charabuddi on cell (248) 202-7313, if no response within 15 proceed with repair.~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
