Measure no. Subject

US 53528266-02 Fault code memory entry 0x21F960, throttle valve

Status date (mm/dd/yy) Status Organization

6/13/13 Accepted US, MOT

Date created (mm/dd/yy) Created by PQM Problem reference

6/13/13 Rainer Wanninger

Release date (mm/dd/yy) Approved by Dealer release

Allow automatic release

Vehicles affected

E series Engine Body

K48 6-ZYL

Production period (from/to) Feedback (all cases relating to

(mm/dd/yy) Comment on production period measure up to) (mm/dd/yy)

8/31/10 / 3/11/12

# Complaint

Engine warning light lights up when the vehicle is in motion. Fault 0x21F960 throttle valve 1

"Comparison fault adapted values" is stored in the fault code memory.

## Cause

Software error

# Measure

Program the Digital Engine Electronics (DME) to the most recent software status

#### Complaint

Fault location Fault type Fault place

Engine running Engine: Dying off

## Cause

# Fault location Fault type Fault place

1 13/61 DME engine control Software error

unit

Repair Task Special Clearance Area

No Powertrain

# Fault code

System State Version

 $\ensuremath{\texttt{©}}$  2002-2013 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.