

SI B51 36 08 Body Equipment November 2013 Technical Service

This Service Information bulletin supersedes SI B51 36 08 dated August 2013.

NEW designates changes to this revision

SUBJECT Outside Door Mirror Moves when Locking or Unlocking the Vehicle

| MODEL NEW | |
|--------------|--|
| E70 | |
| E71 | |
| E72 | |
| E82 | |
| E85 | |
| E86 | |
| E88 | |
| E89 | |
| E90 | |
| E91 | |
| E92 | |
| E93 | |

SITUATION

The door mirror tilts immediately after unlocking or locking. The mirror position does not correspond to the memory position preset by the customer. Pressing the seat memory button typically will return the mirror to the stored position.

CAUSE

Poor electrical contacts of the mirror drive in the mirror housing

NEW INFORMATION

The problem has been integrated into ISTA diagnostics. Complete the diagnosis test plan using the latest ISTA version. The test plan can be accessed via the following path: "Information Search / Function Structure / Body / Mirror / Exterior mirrors / Driver's or passenger side / Exterior Mirror

Malfunction," and then press "Start Search." Select the test plan "AM5102_00010."

CORRECTION

Refer to ISTA diagnosis for the required repair procedure.

WARRANTY INFORMATION Not applicable.

[Copyright ©2013 BMW of North America, Inc.]