

From: [Broadcast Messaging System](#)
To: [DL-BMS Message Monitors](#)
Subject: Delivery Stop - R57 Convertible Top Closing
Date: Thursday, October 31, 2013 3:04:12 PM

Publish Date: October 31, 2013
From: Technical Service
Expiration Date: November 04, 2013

DCSnet Message 
Urgent

Subject: **Delivery Stop - R57 Convertible Top Closing**

To: General Managers, Sales Managers, Service Managers, Service and Parts Directors, Motoring Advisors and Shop Foremen,

A Delivery Stop has been issued on certain 2014 model year MINI Cooper, Cooper S and John Cooper Works Convertibles produced between July and October. During closing, it is possible that the convertible top locating pin is not correctly positioned in the landing plate, at the top of the A-pillar (passenger's side).

Affected vehicles in dealer inventory must not be delivered until a Service Action has been completed. A Service Information bulletin with complete details will be issued by Monday, November 4. No parts are needed for this issue.

A chassis number list of affected vehicles can be found as an attachment to this message.

Sincerely,

Technical Service

Attachments:

 [R57_DelivStop\[8112861a\].pdf](#)  [R57_DelivStop\[8112861a\].pdf](#)

Recipients: All, All Offerings, All Regions, All Areas, All Departments, All Personnel