

**On-car analysis list from July 24th, 2018**  
**please contact VW Helpline before attempting repair**

|                   | Models   | MY    | Engine  | Transmission | Topic  | Customer Complaint  |
|-------------------|--|-------|---|--------------|--|---|
| <b>Powertrain</b> | ATLAS  | 18    | 3.6L (CDVC)   | All          | Engine Oil Leak  | Customer states engine oil leak<br><b>(leak must be from oil pan, front crank sealing flange or vacuum pump)</b><br><b>(untouched vehicles)</b>                                       |
|                   | New Tiguan (LWB)   | 18    | All   | All          | MIL-on P0441   | MIL-on P0441 in the ECM<br><b>(ONLY vehicles located in Florida, Alabama, Georgia, South Carolina, Mississippi)</b>   |
|                   | ATLAS  | 18    | 3.6L (CDVC)   | All          | MIL-on P0030 P0050 P0051 P0133 P0151 P0152                   | MIL-on with any of the following P0030 P0050 P0051 P0133 P0151 P0152 in the ECM<br><b>(untouched vehicles)</b>  |
|                   | ATLAS  | 18    | 3.6L (CDVC)   | All          | MIL-on P054A P0014 P0017 P052A P053A P0010 P0011 P000B P0016 | MIL-on with any of the following P054A P0014 P0017 P052A P053A P0010 P0011 P000B P0016 in the ECM<br><b>(untouched vehicles)</b>  |
|                   | Golf, GTI, SportWagen, Jetta, Beetle, Beetle Convertible, Passat, Tiguan LWB | 16-18 | 1.8T & 2.0T (CPPA,CPLA,CPRA,CPKA,CXBA, CXBB,CXCA,CXCB,DGUA) | All          | Oil Level Thermal Sensor                                     | Yellow oil warning light on with any of the following faults P0196 P0198 B104129 B104135<br><b>(Warning light must be solid not flashing)</b><br><b>(untouched vehicles)</b>          |
|                   | ATLAS  | 18    | 3.6L (CDVC)   | All          | Coolant Leak   | Coolant leak at the coolant pump<br><b>(leak must be from mechanical coolant pump)</b><br><b>(untouched vehicles)</b>   |
| <b>Body</b>       | Golf, GTI, SportWagen  | 17-18 | All   | All          | Side Mirror Glass Cracked                                    | Side mirror glass cracked<br><b>(untouched vehicles)</b>  |
|                   | Tiguan (LWB)   | 18    | All   | All          | Sunshade Binding   | Customer states the sunshade is binding<br><b>(untouched vehicles)</b>  |
|                   | ATLAS  | 18    | All   | All          | Fuel Door Actuator Faulty                                    | Fuel door won't open or fuel door won't unlock.   |
|                   | ATLAS  | 18    | All   | All          | Sunroof Water Leak   | Water leaks from the sunroof/overhead light console area  |
| <b>Chassis</b>    | GTI  | 19    | All   | All          | Damaged Strut Boots  | Damaged strut boots at PDI<br><b>(must be at PDI)</b><br><b>(untouched vehicles)</b>  |
|                   | GTI, SportWagen  | 17-18 | All   | Standard     | Clutch Pedal Noise   | Customer states clutch pedal makes noise during operation<br><b>(untouched vehicles)</b><br><b>(ONLY VINs after HM068470 (GTI))</b><br><b>(ONLY VINs after HM534795 (SportWagen))</b> |
| <b>Electrical</b> | Passat   | 17-18 | All   | All          | Key Inoperative  | Customer states remote key inoperative<br><b>(Cars with Kessy system ONLY)</b><br><b>(MUST be under 12 month, 12,000 miles)</b>   |
|                   | Passat   | 17-18 | All   | All          | Rear Speaker Distortion                                      | Customer states the rear speaker is distorted<br><b>(untouched vehicles)</b>  |