



SI B51 11 16
Body Equipment

May 2016
Technical Service

Service Action: Check and Replace Cup Holder

Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop.

MODEL

F48 (X1)

SITUATION

A cup holder with no clamping elements may have been installed in affected vehicles.

AFFECTED VEHICLES


This Service Action involves certain F48 (X1) vehicles manufactured from March 9, 2016 to March 14, 2016.


Vehicles which require this Service Action to be completed will show it as "Open" when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System) or with the Key Reader.

PROCEDURE

Check the cup holder.

Does the installed cupholder have clamping elements?

	<p>YES - no further measures are required.</p>



NO - Replace the cup holder. See Repair Instructions RA 51 16 150. "Removing and refitting the front storage compartment".

PARTS INFORMATION

Part Number	Description	Quantity
51 16 9 299 529	Cup Holder	1

WARRANTY INFORMATION

Reimbursement for this Service Action will be via normal claim entry utilizing the following information:

Defect Code:	00 51 96 03 00	
Labor Operation:	Labor Allowance:	Description:
00 64 568	3 FRU	Check cup holder (No repair is required) (Plus work)
Or:		
00 64 569	6 FRU	Check and replace cup holder (Plus work)

[Copyright ©2016 BMW of North America, Inc.]