

Surface removal at frame of stowage box/ashtray

Topic number	LI68.20-P-068649
Version	1
Function group	68.20 Center console
Date	08-09-2018
Validity	Valid for vehicles of model series 205/253/213/238 with automatic transmission. Not valid for vehicles with world manufacturer code LE4.
Reason for change	
Reason for block	

Complaint:

Surface removal at frame of stowage box/ashtray.

Attachments	
File	Description
IMG_0102.jpg	Frame of stowage box/ashtray
IMG_0103.jpg	Damage to frame of stowage box/ashtray

Cause:

Insufficient connection of base material to surface material.

Remedy:

Replacement of damaged frame with optimized component parts.

The optimized frames are available individually as a replacement part.

The replacement is done as per WIS document AR68.20-P-0002LWE.

Symptoms
Body / Interior equipment / Stowage box/tray / Warped/twisted/distorted
Body / Interior equipment / Stowage box/tray / Broken
Body / Interior equipment / Stowage box/tray / Scratched
Body / Interior equipment / Ashtray / Does not open
Body / Interior equipment / Ashtray / Does not close

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 205 683 09 00			Trim strip	1	Valid for model series 205/253	X
A 205 683 10 00			Trim strip	1	Valid for model series 205 with WMI (Wireless phone charging, available as of facelift)	X

XENTRY TIPS

A 213 683 06 00		Trim strip	1	Valid for model series 213/238	X
-----------------	--	------------	---	--------------------------------	---

WIS-References

Document number	Title	Note	Allocation
AR68.20-P-0002LWE	Remove/install center console stowage compartment trim element		Remedy

Attachments

XENTRY TIPS

IMG_0102.jpg:



XENTRY TIPS

IMG_0103.jpg:

