

NEWMAR CORPORATION

WARRANTY DEPARTMENT

RECALL SERVICE BULLETIN

DATE ISSUED	MODEL YEAR(S) AFFECTED		RSB #		
10/02/2018	2019		523		
MODEL					
Bay Star Sport	<input type="checkbox"/>	Ventana	<input type="checkbox"/>	Essex	<input type="checkbox"/>
Bay Star	<input type="checkbox"/>	Dutch Star	<input checked="" type="checkbox"/>	King Aire	<input type="checkbox"/>
Canyon Star	<input type="checkbox"/>	Mountain Aire	<input type="checkbox"/>	New Aire	<input type="checkbox"/>
Ventana LE	<input type="checkbox"/>	London Aire	<input type="checkbox"/>	Other	<input type="checkbox"/>
DESCRIPTION					
<p>Newmar Corporation has decided that a defect relating to motor vehicle safety exists in specific motorhomes. NHTSA: 18V 650, TC: 2018-521</p> <p>Issue: The brake pedal assembly could contact the edge of the dashboard trim. This may cause the brake pedal to not fully release and increase the risk of a crash causing injury and/or property damage.</p> <p>Correction: Dealers will reroute the brake adjustment cable.</p> <p>Refer to the attached population list for specific coach and VIN numbers.</p>					
RECOMMENDED ACTION					
<p>Follow the attached work instructions to reroute the cable behind the dash.</p> <p>Flat Rate Code: 18V 650</p> <p>Labor Time: .1 hr</p> <p><u>Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.</u></p>					



Date: October 1, 2018
Re: Newmar Corporation – Motor Vehicle Recall Notification

Subject: Recall Campaign No.: 18V 650

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific Newmar recreational vehicles.

The National Traffic and Motor Vehicle Safety Act requires that each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed on how to contact the National Highway Traffic Safety Administration.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes.

On certain motorhomes, the brake pedal assembly could contact the edge of the dashboard trim. This could cause the brake pedal to not fully release, which could increase the risk of a crash causing injury and/or property damage. Correction: Dealers will reroute the brake adjustment cable.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.

REPAIR PROCEDURE

Newmar will provide the work instructions.

If you should have any questions please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.

Thank you for your cooperation.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

IMPORTANT SAFETY RECALL

This notice applies to your vehicle VIN. # _____

Name

Address

City, State Zip code

Date: October 1, 2018

Motor Vehicle Recall Notification - Recall Campaign No. 18V 650

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes.

On certain motorhomes, the brake pedal assembly could contact the edge of the dashboard trim. This could cause the brake pedal to not fully release, which could increase the risk of a crash causing injury and/or property damage. Correction: Dealers will reroute the brake adjustment cable.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

The Safety Risk

The brake pedal may not fully release, which could increase the risk of a crash causing injury and/or property damage.

WHAT WE WILL DO

Newmar Corporation will provide owners of all affected motorhomes a remedy for the potential defect at no charge for parts or labor. This remedy consists of rerouting the brake adjustment cable. Estimated time for repair is .1 hrs.

As this defect does affect motor vehicle safety, it is recommended that you contact the Newmar service department immediately at **1-800-731-8300**. An associate will assist you in making an appointment to have this repair done by an authorized Newmar Dealer.

Federal regulations require that any vehicle lessor receiving this recall notification must forward a copy of this notice to the lessee within ten days.

If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information, contact Newmar Corporation at:

Service Department
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

Newmar dealers are best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. **HOWEVER**, if you take your vehicle to your dealer on the scheduled date and this condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300.

You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., SE., Washington DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

If you no longer own this vehicle, please furnish us the complete name and address of the person or dealership you sold or traded your vehicle to. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corporation



Date: October 1, 2018
Re: Newmar Corporation – Motor Vehicle Recall Notification

Subject: Recall Campaign No. 2018-521

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the Canada Motor Vehicle Safety Act. Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific Newmar recreational vehicles.

Each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed to contact Transport Canada.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes.

On certain motorhomes, the brake pedal assembly could contact the edge of the dashboard trim. This could cause the brake pedal to not fully release, which could increase the risk of a crash causing injury and/or property damage. Correction: Dealers will reroute the brake adjustment cable.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.

REPAIR PROCEDURE

Newmar will provide the work instructions.

If you should have any questions please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.

Thank you for your cooperation.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

VIN#
Name
Address
City, State Zip code

Date: October 1, 2018
Motor Vehicle Recall Notification - Recall Campaign No. 2018-521

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the Canada Motor Vehicle Safety Act.

REASON FOR THIS RECALL

Newmar Corporation has determined that a defect, which relates to motor vehicle safety, exists in specific motorhomes.

On certain motorhomes, the brake pedal assembly could contact the edge of the dashboard trim. This could cause the brake pedal to not fully release, which could increase the risk of a crash causing injury and/or property damage. Correction: Dealers will reroute the brake adjustment cable.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

WHAT WE WILL DO

Newmar Corporation will provide owners of all affected motorhomes a remedy for the potential defect at no charge for parts or labor. This remedy consists of rerouting the brake adjustment cable at no cost to the customer.

WHAT YOU NEED TO DO

As this defect does affect motor vehicle safety, it is recommended that you contact the Newmar service department immediately at **1-800-731-8300**. An associate will assist you in making an appointment to have this repair done by an authorized Newmar Dealer.

Federal regulations require that any vehicle lessor receiving this recall notification must forward a copy of this notice to the lessee within ten days.

If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information, contact Newmar Corporation at:

Service Department
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

Newmar dealers are best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to your dealer on the scheduled date and this condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300.

If you no longer own this vehicle, please furnish us the complete name and address of the person or dealership you sold or traded your vehicle to. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

NIV
Nom
Adresse
Ville, province, code postal

Date : 1 octobre 2018
Avis de rappel visant un véhicule motorisé – Campagne de rappel n° 2018-521

Madame, Monsieur,

Le présent avis vous est envoyé conformément aux exigences de la *Loi sur la sécurité automobile du Canada*.

MOTIF DU PRÉSENT RAPPEL

Newmar Corporation a déterminé qu'une défaillance relevant de la sécurité automobile existe pour certaines autocaravanes.

Sur certaines autocaravanes, l'ensemble de pédale de frein pourrait entrer en contact avec le bord de la garniture de la planche de bord. Par conséquent, la pédale de frein pourrait ne pas se relâcher complètement, ce qui pourrait augmenter le risque d'accident pouvant causer des blessures ou des dommages matériels. Mesure corrective : Les concessionnaires réacheminèrent le câble de réglage des freins.

Il est impératif que les réparations sur ces autocaravanes soient effectuées immédiatement. Leur utilisation prolongée pose un risque d'accident potentiel.

CE QUE NOUS FERONS

Newmar Corporation fournira aux propriétaires de toutes les autocaravanes concernées une solution gratuite (pour les pièces et la main-d'œuvre) à la défaillance potentielle. Cette solution consistant à réacheminer le câble de réglage des freins sera effectuée gratuitement.

CE QUE VOUS DEVEZ FAIRE

Puisque cette défaillance touche la sécurité automobile, nous vous recommandons de communiquer immédiatement avec le service technique de Newmar en composant le **1-800-731-8300**. Un associé vous aidera à prendre rendez-vous aux fins d'exécution de cette réparation par un centre de service Newmar autorisé.

En vertu de règlements fédéraux, tout donneur à bail d'un véhicule, qui reçoit le présent avis de rappel, est tenu d'en acheminer une copie au preneur à bail dans un délai de dix jours.

Si les réparations ont été effectuées avant réception de la présente lettre, vous pouvez être admissible à un remboursement des frais liés à l'obtention de la solution adoptée avant réception du présent avis. Pour de plus amples renseignements, communiquez avec Newmar Corporation à l'adresse suivante :

Service Department
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

Les concessionnaires Newmar sont les plus à même de fournir du service et d'obtenir des pièces qui assureront une réparation de votre véhicule dans les plus brefs délais. CELA DIT, si vous apportez votre véhicule à votre concessionnaire à la date prévue et que le problème n'est pas résolu à cette date ou dans les cinq jours qui suivent, veuillez communiquer avec le service à la clientèle de Newmar Corporation en composant le 1-800-731-8300.

Si l'autocaravane concernée ne vous appartient plus, nous vous prions de bien vouloir nous fournir le nom complet et l'adresse complète de la personne ou du concessionnaire faisant maintenant office de propriétaire. Nous vous remercions de votre coopération.

Votre sécurité et votre satisfaction par rapport à nos produits Newmar sont importantes pour nous, et nous sommes désolés de tout désagrément occasionné.

Veillez agréer, Madame, Monsieur, l'expression de nos sentiments distingués.

Newmar Corporation

Work Instructions for Recall



1. Inspect the cable attached to the brake pedal. If it is looped outside the dash, proceed with the following steps. If not, the procedure will not need to be performed.



2. Pull out on the bottom of the dash.
3. Tuck the wire up in behind the dash.
4. Release the cable and dash.

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off	Ship Date
USA Units									
607268	4UZFCHE3KCJY2518	2019	DS	DP	4018	FL	2/19/2018	2/27/2018	5/11/2018
607269	4UZACHFE0KCJY2521	2019	DS	DP	3717	FL	2/21/2018	2/28/2018	6/7/2018
607323	4VZAU1D96KC085384	2019	DS	DP	4018	S	5/16/2018	5/24/2018	6/14/2018
607324	4UZFCHE1KCKH5503	2019	DS	DP	4328	FL	5/17/2018	5/24/2018	6/13/2018
607325	4VZAU1D93KC085794	2019	DS	DP	4328	S	7/16/2018	7/23/2018	8/29/2018
607326	4VZAU1D97KC085796	2019	DS	DP	4362	S	7/16/2018	7/24/2018	8/29/2018
607327	4VZAU1D96KC085790	2019	DS	DP	4018	S	7/12/2018	7/19/2018	8/29/2018
607329	4VZAU1D97KC085703	2019	DS	DP	4369	S	6/11/2018	6/19/2018	7/24/2018
607330	4UZFCHE8KCKP8421	2019	DS	DP	4369	FL	6/4/2018	6/12/2018	7/20/2018
607336	4UZFCHE2KCKS5469	2019	DS	DP	4018	FL	6/25/2018	7/11/2018	7/30/2018
607337	4UZACHFE9KCKS5463	2019	DS	DP	3736	FL	6/18/2018	6/25/2018	7/27/2018
607338	4VZAU1D98KC085791	2019	DS	DP	4018	S	7/17/2018	7/24/2018	8/9/2018
607341	4VZAU1D93KC085729	2019	DS	DP	4328	S	6/26/2018	7/11/2018	7/30/2018
607342	4VZAU1D98KC085726	2019	DS	DP	4362	S	6/18/2018	6/26/2018	7/27/2018
607343	4VZAU1D9XKC085596	2019	DS	DP	4328	S	6/5/2018	6/12/2018	7/12/2018
607346	4VZAU1D96KC085904	2019	DS	DP	4018	S	8/6/2018	8/14/2018	8/24/2018
607348	4VZAU1D99KC085797	2019	DS	DP	4328	S	7/17/2018	7/24/2018	8/8/2018
607358	4UZFCHE3KCKT1488	2019	DS	DP	4018	FL	7/9/2018	7/17/2018	8/1/2018
607359	4UZFCHE8KCKT4273	2019	DS	DP	4018	FL	7/10/2018	7/17/2018	8/1/2018
607360	4VZAU1D96KC085725	2019	DS	DP	4018	S	6/11/2018	6/19/2018	7/24/2018
607361	4VZAU1D94KC085870	2019	DS	DP	4002	S	7/30/2018	8/6/2018	8/21/2018
607362	4UZFCHE8KCKU9212	2019	DS	DP	4363	FL	8/6/2018	8/14/2018	8/30/2018
607363	4VZAU1D96KC085871	2019	DS	DP	4363	S	7/23/2018	7/30/2018	8/16/2018
607364	4VZAU1D96KC085949	2019	DS	DP	4002	S	8/13/2018	8/20/2018	9/5/2018
607365	4UZACHFE8KCKV7322	2019	DS	DP	3736	FL	8/13/2018	8/21/2018	9/6/2018
607366	4UZACHFEXKCKR5263	2019	DS	DP	3736	FL	6/14/2018	6/22/2018	7/26/2018
607368	4UZFCHEXKCKU9213	2019	DS	DP	4310	FL	8/7/2018	8/14/2018	8/30/2018
607369	4VZAU1D91KC085874	2019	DS	DP	4310	S	7/30/2018	8/6/2018	8/28/2018
607370	4VZAU1D96KC085952	2019	DS	DP	4326	S	8/7/2018	8/15/2018	8/29/2018
607374	4VZAU1D93KC085746	2019	DS	DP	4369	S	6/26/2018	7/12/2018	7/30/2018
607375	4VZAU1D95KC085747	2019	DS	DP	4369	S	6/26/2018	7/12/2018	8/13/2018
607376	4UZFCHE5KCKP8425	2019	DS	DP	4369	FL	6/12/2018	6/19/2018	7/24/2018
607377	4VZAU1D98KC085872	2019	DS	DP	4369	S	7/23/2018	7/31/2018	8/15/2018
607378	4UZFCHE9KCKS5467	2019	DS	DP	4369	FL	7/18/2018	7/25/2018	8/7/2018
607379	4VZAU1D98KC085905	2019	DS	DP	4369	S	7/30/2018	8/7/2018	8/31/2018
607380	4UZFCHE3KCKT4276	2019	DS	DP	4369	FL	7/18/2018	7/26/2018	8/10/2018
607381	4VZAU1D98KC085953	2019	DS	DP	4369	S	8/8/2018	8/15/2018	8/30/2018
607382	4UZFCHE1KCKT1490	2019	DS	DP	4369	FL	6/27/2018	7/12/2018	8/6/2018
607383	4UZFCHE7KCKT1493	2019	DS	DP	4369	FL	7/31/2018	8/7/2018	8/24/2018
607384	4VZAU1D9XKC085906	2019	DS	DP	4369	S	7/31/2018	8/7/2018	8/23/2018
607385	4VZAU1D93KC085908	2019	DS	DP	4369	S	8/1/2018	8/8/2018	8/22/2018
607386	4UZFCHE2KCKV2400	2019	DS	DP	4369	FL	7/23/2018	7/31/2018	8/14/2018
607387	4UZFCHE5KCKT8085	2019	DS	DP	4369	FL	7/24/2018	7/31/2018	8/14/2018
607392	4UZFCHEXKCKT4274	2019	DS	DP	4018	FL	7/11/2018	7/18/2018	8/14/2018
607393	4VZAU1D99KC085749	2019	DS	DP	4363	S	7/12/2018	7/19/2018	8/9/2018

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off	Ship Date
607394	4VZAU1D95KC085702	2019	DS	DP	4369	S	6/12/2018	6/20/2018	7/24/2018
607395	4VZAU1D95KC085814	2019	DS	DP	4018	S	7/16/2018	7/23/2018	8/8/2018
607396	4UZFCHFE9KCKV2393	2019	DS	DP	4018	FL	8/8/2018	8/16/2018	8/30/2018
607398	4UZFCHFE8KCKU4835	2019	DS	DP	4369	FL	7/27/2018	8/6/2018	8/16/2018
607399	4UZFCHFE1KCKT8083	2019	DS	DP	4369	FL	7/24/2018	8/1/2018	8/10/2018
607400	4UZFCHFE8KCKR5266	2019	DS	DP	4363	FL	6/12/2018	6/20/2018	7/24/2018
607414	4VZAU1D99KC085699	2019	DS	DP	4369	S	6/5/2018	6/13/2018	7/20/2018
607415	4VZAU1D9XKC085744	2019	DS	DP	4018	S	6/19/2018	6/26/2018	7/27/2018
607424	4UZFCHFE1KCKP0998	2019	DS	DP	4369	FL	5/30/2018	6/7/2018	7/12/2018
607425	4UZFCHFE6KCKP8420	2019	DS	DP	4363	FL	6/1/2018	6/8/2018	7/12/2018
607441	4UZACHFE7KCKT1486	2019	DS	DP	3717	FL	6/27/2018	7/13/2018	7/31/2018
607444	4UZFCHFEXKCKR5267	2019	DS	DP	4369	FL	6/13/2018	6/20/2018	7/26/2018
607445	4UZFCHFEXKCKT8082	2019	DS	DP	4369	FL	6/28/2018	7/13/2018	8/14/2018
607446	4UZFCHFE1KCKR5268	2019	DS	DP	4369	FL	6/13/2018	6/21/2018	7/27/2018
607447	4UZFCHFE8KCKP8418	2019	DS	DP	4018	FL	6/5/2018	6/13/2018	7/16/2018
607448	4UZFCHFE5KCKS5465	2019	DS	DP	4369	FL	6/19/2018	6/27/2018	7/27/2018
607449	4UZFCHFE4KCKP8416	2019	DS	DP	4018	FL	6/6/2018	6/13/2018	7/16/2018
607451	4UZFCHFEXKCKP0997	2019	DS	DP	4363	FL	6/6/2018	6/14/2018	7/18/2018
607453	4UZFCHFE1KCKP8423	2019	DS	DP	4369	FL	6/7/2018	6/14/2018	7/13/2018
607458	4UZFCHFE1KCKT4275	2019	DS	DP	4328	FL	7/18/2018	7/26/2018	8/10/2018
607459	4UZFCHFE2KCKU4832	2019	DS	DP	4018	FL	7/19/2018	7/26/2018	8/20/2018
607460	4UZFCHFE5KCKT1492	2019	DS	DP	4369	FL	7/11/2018	7/18/2018	8/13/2018
607462	4VZAU1D98KC085936	2019	DS	DP	4328	S	8/1/2018	8/9/2018	8/23/2018
607463	4VZAU1D90KC085798	2019	DS	DP	4369	S	7/19/2018	7/27/2018	8/10/2018
607464	4UZFCHFE1KCKU4837	2019	DS	DP	4369	FL	8/1/2018	8/9/2018	8/29/2018
607466	4UZFCHFE0KCKV2394	2019	DS	DP	4328	FL	8/14/2018	8/21/2018	9/6/2018
607467	4UZFCHFE8KCKV2398	2019	DS	DP	4369	FL	8/9/2018	8/16/2018	8/31/2018
607472	4VZAU1D91KC085700	2019	DS	DP	4369	S	6/7/2018	6/15/2018	7/20/2018
607473	4VZAU1D95KC085697	2019	DS	DP	4018	S	6/8/2018	6/18/2018	7/24/2018
607477	4VZAU1D97KC085815	2019	DS	DP	4018	S	7/24/2018	8/1/2018	8/20/2018
607478	4VZAU1D9XKC085792	2019	DS	DP	4369	S	7/12/2018	7/20/2018	8/6/2018
607480	4VZAU1D90KC085817	2019	DS	DP	4369	S	7/24/2018	8/1/2018	8/15/2018
607541	4UZFCHFEXKCKV2399	2019	DS	DP	4369	FL	8/14/2018	8/22/2018	9/5/2018
607557	4VZAU1D90KC086000	2019	DS	DP	4369	S	8/9/2018	8/17/2018	8/31/2018
607641	4UZFCHFE6KCKU9211	2019	DS	DP	4363	FL	8/2/2018	8/9/2018	9/6/2018
607645	4UZACHFE3KCKT4272	2019	DS	DP	3717	FL	7/13/2018	7/20/2018	9/6/2018
607728	4VZAU1D9XKC085873	2019	DS	DP	4369	S	7/25/2018	8/6/2018	8/16/2018
607730	4VZAU1D93KC085701	2019	DS	DP	4369	S	6/8/2018	6/15/2018	7/19/2018
607749	4VZAU1D91KC085938	2019	DS	DP	4328	S	8/2/2018	8/9/2018	8/31/2018
607750	4UZFCHFE4KCKR5264	2019	DS	DP	4018	FL	6/20/2018	6/27/2018	7/27/2018
607752	4VZAU1D91KC085745	2019	DS	DP	4018	S	6/20/2018	6/28/2018	7/27/2018
607758	4VZAU1D99KC085816	2019	DS	DP	4369	S	7/19/2018	7/27/2018	8/10/2018
607762	4VZAU1D95KC085795	2019	DS	DP	4362	S	7/20/2018	7/27/2018	8/29/2018
607763	4VZAU1D91KC085793	2019	DS	DP	4328	S	7/20/2018	7/30/2018	8/29/2018
607781	4UZACHFE0KCKV2390	2019	DS	DP	3717	FL	8/2/2018	8/10/2018	8/30/2018
607791	4UZFCHFE3KCKP8424	2019	DS	DP	4369	FL	6/8/2018	6/18/2018	7/18/2018

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off	Ship Date
607792	4UZFHFE3KCKR5269	2019	DS	DP	4369	FL	6/21/2018	6/28/2018	7/27/2018
607797	4UZACHFEXKCKP8415	2019	DS	DP	3736	FL	6/4/2018	6/11/2018	7/18/2018
607814	4UZFHFE0KCKU4831	2019	DS	DP	4018	FL	7/26/2018	8/2/2018	8/15/2018
607821	4UZFHFE4KCKU9210	2019	DS	DP	4369	FL	8/3/2018	8/10/2018	8/23/2018
607823	4UZFHFE3KCKS5464	2019	DS	DP	4369	FL	6/14/2018	6/21/2018	7/25/2018
607834	4VZAU1D9XKC085789	2019	DS	DP	4002	S	6/21/2018	6/28/2018	7/26/2018
607849	4VZAU1D98KC085869	2019	DS	DP	4018	S	7/27/2018	8/3/2018	8/17/2018
607855	4UZFHFEKCKP8422	2019	DS	DP	4328	FL	6/21/2018	7/9/2018	7/27/2018
607858	4UZFHFE3KCKT8084	2019	DS	DP	4369	FL	6/28/2018	7/16/2018	8/13/2018
607889	4VZAU1D99KC085704	2019	DS	DP	4369	S	6/15/2018	6/22/2018	7/27/2018
607890	4VZAU1D96KC085935	2019	DS	DP	4018	S	8/10/2018	8/17/2018	8/31/2018
607901	4UZFHFE1KCKT1487	2019	DS	DP	4018	FL	6/28/2018	7/16/2018	8/2/2018
607902	4VZAU1D93KC085939	2019	DS	DP	4328	S	8/3/2018	8/10/2018	8/24/2018
607903	4UZFHFE7KCKS5466	2019	DS	DP	4369	FL	6/22/2018	7/9/2018	7/30/2018
607904	4UZFHFE3KCKT1491	2019	DS	DP	4328	FL	7/9/2018	7/16/2018	8/7/2018
607938	4UZFHFE6KCKU9208	2019	DS	DP	4018	FL	7/30/2018	8/7/2018	8/21/2018
607939	4UZFHFEKCKP8419	2019	DS	DP	4018	FL	6/8/2018	6/15/2018	7/25/2018
607944	4UZFHFE6KCKP8417	2019	DS	DP	4018	FL	6/15/2018	6/22/2018	7/27/2018
607993	4VZAU1D91KC085728	2019	DS	DP	4363	S	6/22/2018	7/10/2018	7/31/2018
608016	4VZAU1D97KC085748	2019	DS	DP	4369	S	7/9/2018	7/16/2018	8/2/2018
608035	4UZACHFE4KCKV2389	2019	DS	DP	3717	FL	8/10/2018	8/20/2018	8/30/2018
608058	4UZACHFE1KCKU9207	2019	DS	DP	3736	FL	7/27/2018	8/6/2018	8/22/2018
608063	4VZAU1D97KC085698	2019	DS	DP	4018	S	6/11/2018	6/18/2018	7/23/2018
608064	4VZAU1D92KC085950	2019	DS	DP	4369	S	8/3/2018	8/13/2018	8/30/2018
608065	4VZAU1D94KC085951	2019	DS	DP	4369	S	8/6/2018	8/13/2018	8/30/2018
608066	4VZAU1D9XKC085937	2019	DS	DP	4369	S	8/3/2018	8/13/2018	8/28/2018
608067	4UZFHFE6KCKR5265	2019	DS	DP	4018	FL	6/15/2018	6/25/2018	8/23/2018
608068	4UZFHFE5KCKT1489	2019	DS	DP	4369	FL	6/25/2018	7/10/2018	7/31/2018
608072	4VZAU1D91KC085907	2019	DS	DP	4310	S	7/31/2018	8/8/2018	8/30/2018
608074	4VZAU1D9XKC085727	2019	DS	DP	4369	S	6/15/2018	6/25/2018	7/27/2018
608075	4UZFHFE4KCKU4833	2019	DS	DP	4369	FL	7/20/2018	7/30/2018	8/13/2018
608076	4UZFHFE6KCKU4834	2019	DS	DP	4362	FL	7/26/2018	8/2/2018	8/15/2018

Canadian units

607243	4VZAU1D93KC084340	2019	DS	DP	4328	S	1/22/2018	1/30/2018	6/29/2018
607389	4VZAU1D98KC085595	2019	DS	DP	4369	S	6/1/2018	6/11/2018	7/12/2018
607500	4UZACHFE7KCKT8079	2019	DS	DP	3736	FL	7/25/2018	8/1/2018	8/17/2018
607505	4UZFHFE8KCKT8081	2019	DS	DP	4018	FL	7/13/2018	7/20/2018	8/13/2018
607856	4UZACHFE6KCKU4830	2019	DS	DP	3736	FL	7/27/2018	8/3/2018	8/21/2018