



SERVICE BULLETIN

Classification: BR18-009	Reference: NTB18-079	Date: November 13, 2018
-----------------------------	-------------------------	----------------------------

2017-2019 ARMADA; FRONT DISC BRAKE ROTOR SERVICE INFORMATION

APPLIED VEHICLES: 2017-2019 Armada (Y62)

SERVICE INFORMATION

For the Applied Vehicles, the minimum wear thickness for the front disc brake rotors specified in the Electronic Service Manual (ESM) is incorrect.

The correct minimum wear thickness is 28.5 mm (1.122 inches).

The affected ESMs will be corrected. Until then, do not reference these ESMs for this specification. Refer to the specification stated above.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
November 13, 2018	NTB18-079	Original bulletin published

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.