



Volvo Models

Volvo Model VNX , VNL

Engine family

Engine family Cummins

** SOLUTION **

Title Volvo Chassis - **Equipped With A Cummins Engine** - Cummins Fuel Pump Timing Correction to Reduce Engine Noise; Drone Noise at 1500 RPM and Increases With Engine Load - **US10 And Newer Emissions, Common Model Year 2014 And Newer**

Cause Incorrect fuel pump timing.

Solution For more information regarding Cummins TSB170124, Fuel Pump Timing Correction to Reduce Engine noise, refer to the following attachment. [TSB170124](#)

NOTE: For the most current troubleshooting and repair information refer to Cummins QuickServe®. This information is current as of October 2018.

Solution visibility **Dealer distribution**

Function(s)/component(s) affected

Function affected Documentation , fuel supply , fuel system

Function Group

Function Group 233 fuel pump, filter and strainer

Customer effect

Main customer effect noise , vibration , diagnostics/methodology

Noise whine

Fluid implicated fuel

Conditions

Vehicle operating mode on start-up , when driving

Frequency of occurrence of problem always

Administration

Author RU1991V

Dealer ID A241298

Last modified by A241298

Creation date 18-10-2018 16:10

Date of last update 06-11-2018 21:11

Status

Published
