



# Technical Service Bulletin

SUBJECT:			No: <b>TSB-18-32-001</b>
<b>TORQUE UPDATES: UNITS OF TIGHTENING TORQUE &amp; NUMERICAL VALUE FOR POWER PLANT MOUNT - SERVICE MANUAL REVISION</b>			DATE: <b>December 2018</b>
			MODEL: <b>See below</b>
<b>CIRCULATE TO:</b>	<input type="checkbox"/> GENERAL MANAGER	<input checked="" type="checkbox"/> PARTS MANAGER	<input checked="" type="checkbox"/> TECHNICIAN
<input checked="" type="checkbox"/> SERVICE ADVISOR	<input checked="" type="checkbox"/> SERVICE MANAGER	<input checked="" type="checkbox"/> WARRANTY PROCESSOR	<input type="checkbox"/> SALES MANAGER

## PURPOSE

This TSB updates the Power Plant Mount section of the affected Service Manuals to correct the tightening torque for the Crossmember Removal Service Points.

## AFFECTED VEHICLES

- 2008 - 2011 Lancer
- 2009 - 2011 Lancer Sportback

## AFFECTED SERVICE MANUAL

- 2008-2010 Lancer Service Manual, Group 32 - Power Plant Mount
- 2009-2010 Lancer Sportback Service Manual, Group 32 - Power Plant Mount
- 2011 Lancer/Lancer Sportback Service Manual, Group 32 - Power Plant Mount



Please make the indicated changes to the 2008 - 2010 Lancer, 2009 & 2010 Lancer Sportback, 2011 Lancer/ Lancer Sportback Evolution Service Manual, Group 32 - Power Plant Mount -> Crossmember -> Removal Service Points.

