



GROUP
CLI

MODEL
2017-2018MY
Sportage (QL)

NUMBER
041

DATE
October 2017

TECHNICAL SERVICE BULLETIN

SUBJECT: SERVICE ACTION: EVAPORATOR TEMPERATURE
SENSOR AND/OR ECV REPLACEMENT (SA309)

This bulletin provides the procedure to replace the Evaporator Temperature Sensor and /or ECV (External Control Valve) on 2017-2018MY Sportage (QL) vehicles produced from December 1, 2015 through July 18, 2017, which may exhibit indoor air conditioning performance. Kia is requesting the completion of this Service Action on affected vehicles including those in dealer stock, prior to delivery.

To correct/prevent this concern, follow the procedure outlined in this bulletin.

Before conducting the procedure, verify that the vehicle is included in the list of affected VINs.

Service Action #	Production Range	Action	Page
SA309A	December 1, 2015 through July 18, 2016	ECV and Evaporator Temperature Sensor Replacement (Refrigerant Recovery and Charging)	2
SA309	December 1, 2016 through July 18, 2017	Evaporator Temperature Sensor Replacement	4



ECV



Evaporator Temperature Sensor

* NOTICE

A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on WebDCS (Service → Warranty Coverage → Warranty Coverage Inquiry → Campaign Information). Not completed Recall / Service Action reports are available on WebDCS (Consumer Affairs → Not Completed Recall → Recall VIN → Select Report), which includes a list of affected vehicles.

This issue number is SA309.

File Under: <Climate>

Circulate To: General Manager Service Manager Parts Manager
 Service Advisors Technicians Body Shop Manager Fleet Repair