

**Mack Models**

Mack Model CH , RB , DM , CHN , CL , CT , CV , CX , CXM , LE , MR , RD

**** SOLUTION ****

Title V-MAC III - Smart Fan Will Not Disengage

Cause To assist in the diagnostic process, the operation and control of each smart fan component .

Solution For more information regarding V-MAC III - Smart Fan Will Not Disengage click [here](#).

Solution visibility [Dealer distribution](#)

Function(s)/component(s) affected

Function affected engine control unit , fan drive , thermostat , engine cooling fan

Function Group

Function Group 263 fan, fan shroud and clutch , 364 electrical item

Customer effect

Main customer effect engine speed , temperature , efficiency/abnormal behavior , power

Administration

Author A241298

Dealer ID A241298

Last modified by A241298

Creation date 18-12-2018 16:12

Date of last update 18-12-2018 16:12

Status Published
