

**Mack Models**

Mack Model CXN , CH , RB , DM , CHN , CL , CT , CV , CX , CXM , LE , MR , RD

**** SOLUTION ****

Title V-MAC III - Speedometer Not working After Reprograming

Cause The automatic transmission VECU file (1MS314P2 or 1MS318P2) has been turned on by mistake.

Solution The automatic transmission VECU file (1MS314P2 or 1MS318P2) has been turned on by mistake, instead of using the standard VECU file (1MS314 or 1MS318). Contact the Mack Truck, Inc. Product Support group to have the proper VECU file activated.

Solution visibility [Dealer distribution](#)

Function(s)/component(s) affected

Function affected MID 144 – VECU , VECU , VMAC

Function Group

Function Group 170 General - Programming, Data Monitor, Vehicle Information

Customer effect

Main customer effect acceleration/speed , calibration/programming/pairing/missing operation

Administration

Author A241298

Dealer ID A241298

Last modified by A241298

Creation date 19-12-2018 20:12

Date of last update 20-12-2018 18:12

Status Published
