

Technical Service Bulletin

| SUBJECT: | | | No: | TSB-19-33-001 |
|----------|---------------------------------|-------------------------------|---------|------------------|
| | OL UPDATE FOR DUST COVER REF | - | DATE: | January 2019 |
| | | | MODEL | See below |
| SERV | ICE MANUAL REV | /ISIUN | TIODEL. | |
| SERV | [] GENERAL MANAGER | (ISIUN [X] PARTS MANAGER | | [X] TECHNICIAN |

PURPOSE

This TSB updates the Front Suspension section of the affected Service Manuals to update the special service tool used in replacement of the Lower Arm Ball Joint Dust Cover.

AFFECTED VEHICLES

- 2012 2017 i-MiEV
- 2008 2015 Lancer
- 2009 2015 Lancer Sportback
- 2007 2016 Outlander
- 2011 2015 Outlander Sport/RVR

AFFECTED SERVICE MANUALS

- 2012 2017 i-MiEV Service Manual, Group 33-Front Suspension
- 2008 2015 Lancer Service Manual, Group 33-Front Suspension
- 2009 2015 Lancer Sportback Service Manual, Group 33-Front Suspension
- 2007 2016 Outlander Service Manual, Group 33-Front Suspension
- 2011 2015 Outlander Sport/RVR Service Manual, Group 33-Front Suspension

Page 2 of 5 TSB-19-33-001

Please make the indicated changes below to the 2012 - 2017 i-MiEV Service Manual, Group 33-Front Suspension -> Special Tools.

SPECIAL TOOLS


| <correct></correct> | SPECIAL TOOLS | | | |
|---------------------|---------------|-----------------------|--------------|--|
| ΤοοΙ | | Tool number and name | Supersession | Application |
| | | MB992216 Installer | - | Lower arm ball joint dust cover installation |

<Incorrect>

| Tool | Tool number and name | Supersession | Application |
|----------|--|--|--|
| МБ990800 | MB990800 Ball joint dust cover installer | MB990800-01or General service tool | Lower arm ball joint dust cover installation |

Please make the indicated changes below to the 2012 - 2017 i-MiEV Service Manual, Group 33-Front Suspension -> Lower Arm -> Lower Arm Ball Joint Dust Cover Replacement.





<Incorrect>

<Correct>

Please make the indicated changes below to Group 33-Front Suspension -> Special Tools, in the following Service Manuals:

- 2008 2015 Lancer
- 2009 2015 Lancer Sportback
- 2007 2016 Outlander
- 2011 2015 Outlander Sport/RVR

SPECIAL TOOLS

| ΤοοΙ | Tool number and name | Supersession | Application |
|------|---------------------------------------|---|--|
| | MB992216 Installer | - | Lower arm ball joint dust cover installation |
| | MD998812 Installer cap | MIT304180-A or General service tool | Lower arm ball joint dust cover installation |
| | MD998813 Installer-100 | MIT304180-A or General service tool | |
| | MD998823 Installer adapter (48) | _ | |

| < | Incorrect> | |
|---|------------|--|
| | | |

| ТооГ | Tool number and name | Supersession | Application |
|----------|--|--|--|
| MB990800 | MB990800 Ball joint dust cover installer | MB990800-01or General service tool | Lower arm ball joint dust cover installation |

1

Please make the indicated changes below to Group 33-Front Suspension -> Lower Arm -> Lower Arm Ball Joint Dust Cover Replacement, in the following Service Manuals:

- 2008 2015 Lancer
- 2009 2015 Lancer Sportback
- 2007 2016 Outlander
- 2011 2015 Outlander Sport/RVR

LOWER ARM BALL JOINT DUST COVER REPLACEMENT

