

Latest Vehicle Concern Fixes



Check Engine Lamp with DTC P0496 stored

Customer Voice:

- The Check Engine Lamp is on.

Technical Description:

- DTC P0496 is stored in the PCM.
- The fuel tank leak test routine returns a passing result.
- This is caused by a bug in the software and is set when the gas cap is removed for refueling prior to the ignition being turned off.

Status:

- Updated PCM software is available for all vehicles equipped with AJ20P.
- Updated PCM software will be available in the coming months for vehicles equipped with AJ126 and AJ133.

XCL 18 & 19MY

