



Preliminary Information

PIT5302B Turn Signal Indicator Does Not Match Audible Warnings (Click-Clack)

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Equinox	2010 - 2017	ALL	ALL	ALL	ALL
GMC	Terrain	2010 - 2017	ALL	ALL	ALL	ALL

Supersession Statement

This PI was superseded to update Model years. Please discard PIT5302A.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition / Concern

Customer may have a concern where the turn signal indicators on the IPC do not match the audible warnings (Click-Clack) from the speaker.

Recommendations / Instructions

IMPORTANT: Do NOT replace or update software in any control modules. Inspect battery condition with the GR8 (EL-50313) and verify the charging system is operating correctly.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4041512	Battery Charging and Testing	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.



GENERAL MOTORS