

Service Bulletin

TECHNICAL

Subject: Ride Control Mode Will Not Extend Over Ignition Cycle from Sport Mode, Defaults to Tour

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to	Engine.	Transmission.
Cadillac	ATS	2018	2019			3.6L	
	CTS					(RPO LGX)	

Involved Region or Country	North America and N.A. Export Regions	
Condition	Some customers may comment that the ride control mode will not extend over ignition cycle from sport mode, defaults to tour mode.	
Cause	This condition may be caused by a software anomaly.	
Correction	Technicians should reprogram the engine control module (ECM).	

Service Procedure

Important: Stable battery voltage is critical during programming. Any fluctuation, spiking, over voltage or loss of voltage will interrupt programming. Install the EL-49642 SPS Programming Support Tool (GM Dealer Equipment Item #PSC-550) to maintain system voltage. If not available, connect a fully charged 12 V jumper or booster pack disconnected from the AC voltage supply. DO NOT connect a battery charger.

Refer to K20 Engine Control Module: Programming and Setup with SPS in SI.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2810075	Engine Control Module Reprogramming with SPS	Use Published Labor Operation Time

Version	2
Modified	Released October 18, 2018
	November 26, 2018 – Updated the Subject and added the ATS model.

