

XENTRY TIPS

Model series 257: In the Edition 1, the Welcome graphic is not displayed in the instrument cluster with the specific Edition animation.

Topic number	LI54.30-P-068844
Version	2
Function group	54.30 Instrument cluster, display instruments, hazard warning device
Date	01-30-2019
Validity	Model series 257 with code P19 ("Edition 1" special model) and code B01 (48 V technology)
Reason for change	Remedy adapted.
Reason for block	

Complaint:

In the "Edition 1" model series 257, the Welcome graphic is not displayed in the instrument cluster with the specific edition animation.

Cause:

In vehicles with 48 V on-board electrical system, the animation is disabled.

Remedy:

Perform SCN coding of the instrument cluster. Use the very latest XENTRY addons.

Symptoms
Communication/information / Information display / Displays / Multifunction display / Multifunction display, menu / Menu items missing
Communication/information / Information display / Displays / Multifunction display / Multifunction display, menu / Incomplete display
Communication/information / Information display / Displays / Multifunction display / Multifunction display, menu / Faulty display

Control unit/fault code		
Control unit	Fault code	Fault text
A1 - Instrument cluster (IC) (IC213)	-	-