

Reference	SSM74277
Models	F-TYPE / X152
Title	Cargo shelf - Rubber strip adrift
Category	Body
Last modified	18-Feb-2019 00:00:00
Symptom	107000 Interior Trim
Attachments	X152 Loadspace.pdf (X152 Loadspace.pdf)
Content	<p>Issue: Rear cargo cover front rubber strip adrift.</p> <p>Cause: The front rubber strip can become dislodged through external influences, please see attached file for examples when adrift and with it correctly fitted.</p> <p>Action: Should a customer report the above concern then simply refit the rubber to the loadspace cover. Instances have occurred where loadspace cover have been replaced for this concern which is not required.</p> <p>Technicians - Please rate this SSM and provide comments so that future communications can be improved.</p> <p>1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.</p> <p>3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.</p> <p>5 = Excellent – All required information provided to resolve the customer concern.</p>